


Support maintenance and cleaning

Support ultrasonic cleaning:



A special detergent is inserted into the ultrasonic cleaning tank to remove contamination and protect from oxidation at a temperature of 45-50°C.



The plant consist of a heated ultrasonic tank
Not need to rinsing.
Lastly, it is necessary to protect it by emulsion oil.
The support are ready to be used again, with a considerable saving on time.
Max time 2-5 h.

CLEANING OF NONWOVENS PLANT

UESSETI 2000 Srl Via Monfalcone 7 20092 Cinisello Balsamo (MI)
tel.02.66014628—fax.02.66014630
uesseti@uesseti.com

UESSETI 2000® S.r.l.

www.uesseti.com